

CERTIFICATE

Certificate no.

18-SIL-0010024-01-TIC

WE HEREBY CERTIFY THAT

Product description

EL-O-MATIC™ PNEUMATIC RACK AND PINION SPRING

RETURN ACTUATORS

Models

SERIES F (up to and including size 0600)

EMERSON AUTOMATION SOLUTIONS

Manufacturer

Eekboerstraat 28A 7575 AX Oldenzaal The Netherlands

IS IN COMPLIANCE WITH THE REQUIREMENTS OF THE STANDARDS

IEC 61508 Parts 1-7:2010

AS RESULT OF THE ASSESSMENT ACCORDING TO THE PROVISION

SET OUT IN THE ABOVE-MENTIONED STANDARDS

Summary Report no. RC-0818-SIL-TIC-PC-0010024-18-02

Expiry date

19.08.2021

Note

This certificate is issued upon the request of the manufacturer as voluntary certification; it does

not include the production surveillance.

This certificate does not allow the manufacturer to use the safety mark of TÜV INTERCERT.



Dipl. Ing. Feridoon Sergizzarea

Reggio Emilia, 20.08.2018

TÜV INTERCERT Certification Body

Туре	A
HFT	0
Safety functions	 Delivery of a full stroke (90° ± tolerance) driven by the spring, with power fluid exhausted from the cylinder through the control system
Mode of operation	Low Demand Mode

Random failure rates						
F - No PST	1	2,55E-08	0,00E+00	0,00E+00		
F - With PST	1	2,29E-09	2,32E-08	0,00E+00		

		Tii√			
	1	NTER CERT			
		SAAR			
CF	२ Т	F	C	Δ -	T F
					l L
ANNE	X to Certifica	ate no. 18-SI	L-001002	4-01-TIC	
Туре	A				
HFT	0	full atralia (00° 1 t	-l\ d=:-		in aith
Safety functions		full stroke (90° ± t chausted from the			
Mode of operation	Low Demand Mo	ode			
	Ra	ndom failure rate	es		
Configuration		Safety function	λ _{DU} [1/h]	λ _{DD} [1/h]	λ _s [1/h]
F - No PST		1	2,55E-08	0,00E+00	0,00E+00
F - With PST		1	2,29E-09	2,32E-08	0,00E+00
Systematic capability	3 (Route 1 _s ap	oplied)			
	Route 1 _H :	Applied	Route 2	H: Applie	ed
Architectural constraints	single charup to SIup to SI	an be used in: nnel configuration L 2 without exterr L 3 considering e nnel configuration	nal diagnostic xternal diagno	ostic tests	
Remarks:	use, lifetim cause fac	details, including ne, failure rates tr ctors and syste to Safety Manual	aceability, me ematic capa	ean repair tim	es, commo
	FNI	D OF CERTIFICA	TF		



TÜV INTERCERT S.r.l. – Group of TÜV Saarland

on behalf of

TÜV INTERCERT GmbH – Group of TÜV Saarland

Report no.: RC-0818-SIL-TIC-PC-0010024-18-02

SIL SUMMARY REPORT

IEC 61508-1/7: 2010

EL-O-Matic™ pneumatic rack and pinion spring return actuators

Series F

Emerson Automation Solutions
Eekboerstraat 28A
7575 AX Oldenzaal
The Netherlands

Date: 2018-08-07 Place: Reggio Emilia

Author Carlo Tarantola

Signature

This document is only valid in its entirety, without any change.

TÜV INTERCERT S.r.l. – Group of TÜV Saarland Report no.: RC-0818-SIL-TIC-PC-0010024-18-02

Via Cecati 1/1 Rev.:

I-42123 Reggio Emilia

e-mail: info@tuvintercert.it

Job no.: TIC-PC-0010024-18-0077-18

Order no: Emerson order dated 2018-06-13

Page 1 of 7



1 INTRODUCTION

This report summarises the results of the assessment according to standards:

IEC 61508-1/7: 2010

for the following products:

EL-O-Matic™ pneumatic rack and pinion spring return actuators series F

NOTES:

- This report is related to the assessment of EL-O-Matic[™] pneumatic rack and pinion spring return actuators series F up to and including size 0600.
- The results of this report can be used for the assessment of a complete Safety Instrumented System.

2 ASSESSMENT AND RESULTS

Product identification					
Device	EL-O-Mationactuators	™ pneumatic rack and pinion spring re	turn		
Series	F				
Models / configurations	F - No PST F - With PS	Т			
Safety function(s)					
1.	with power control syst NOTE: con the safety f can be con	a full stroke (90° ± tolerance) driven by the spr fluid exhausted from the cylinder through the em. sidering the functioning of the actuator to perfo unction(s), the safety functions "close" and "op sidered equivalent. The safety function is in bo n by the spring.	orm en"		
Mode of operation of the safety function(s)	Low demand mode				
Reference standards					
General functional safety standard	IEC 61508-	1/7: 2010			
Product specific functional safety standard	None				
Assessment phases					
Management of functional safety / functional safety planning	Assessed	A functional safety audit of the management systems and of the functional safety planning conducted to document and highlight that the development of the product under considerati is compliant with IEC 61508.			
Safety requirements specification	Assessed	The Safety requirements specification is assessed with respect to its consistency and completeness in a comparison with the applicable requirements of IEC 61508.			

TÜV INTERCERT S.r.l. – Group of TÜV Saarland

Via Cecati 1/1

I-42123 Reggio Emilia e-mail: <u>info@tuvintercert.it</u> Report no.: RC-0818-SIL-TIC-PC-0010024-18-02

Rev.: 00

Job no.: TIC-PC-0010024-18-0077-18
Order no: Emerson order dated 2018-06-13



Design	Assessed	 The assessment of the design included the following aspects: Quantifiable aspects: random failure rates, DC, SFF, PFD_{AVG}, β factors, MRT, PTC, architectural constraints Non-quantifiable aspects: behaviour of the safety function under fault conditions, safety-related software (not applicable to the product under consideration), systematic failures, behaviour under environmental conditions See below for the results.
Verification and Validation	Assessed	The verification and validation activities performed by the manufacturer include review, analysis and tests.
Information for use	Assessed	 The assessment covers: the installation, operation and maintenance instructions (IOM Manual) the particular instructions required by Annex D of IEC 61508 Part 2 (Safety Manual)
Modification	Assessed	Procedures for modification activity are described in specific documents, referenced in the safety planning.
Results		
Selected assessment routes	 For Sys Furthermor 7.4.10.7 of fulfilled, as the pro- and is of the pro- (includi suitabil declare 	duct has a restricted and specified functionality designed to perform specified safety functions duct has an adequate documentary evidence ng extensive operating experience and results of ity analysis and testing), sufficient to claim the d failure rates nufacturer has an effective system for reporting
Element type (A or B)	Type A	
HFT	The produc	t has a single channel configuration, HFT=0.

Via Cecati 1/1 I-42123 Reggio Emilia e-mail: info@tuvintercert.it

Rev.: Job no.: TIC-PC-0010024-18-0077-18 Order no: Emerson order dated 2018-06-13



Random failure rates	FMEDA, integra	The determination of random failure rates is performed with a FMEDA, integrated with field feedback, according to IEC 61508 Part 2 Par. 7.4.4.3.3, using the Bayesian approach.					
Configuration	Safety function	λ _{DU} [1/h]	λ _{DD} [1/h]	λ _s [1/h]			
F - No PST	1	2,55E-08	0,00E+00	0,00E+00			
F - With PST	1	2,29E-09	2,32E-08	0,00E+00			
Spurious trip rate	generate spurio Part" and not "S no part in imple 3.6.16 of IEC 6 ² estimated.	NOTE: failures of components of the cylinder which can generate spurious trips shall be correctly classified as "No Part" and not "Safe", being related to components that "play no part in implementing the safety function" (see definition 3.6.16 of IEC 61508 Part 4). Anyway the spurious trip rate is					
DC	Diagnostic is on PST.	The product does not include internal diagnostics. Diagnostic is only be possible via external means, e.g. with a					
SFF	Considering tha 61508 Part 4: SFF=0 without SFF>0 with to definition	Considering that λ_s =0, according to definitions 3.6.15 of IEC					
PFD _{AVG}	As the PFD _{AVG} version the PTC and the product-dependence product relevant Anyway, PFD _{AV}	As the PFD _{AVG} value depends also on the test intervals and on the PTC and the coverage of external tests, which are not product-dependant quantities, the PFD _{AVG} values are not product relevant quantities, while λ values are. Anyway, PFD _{AVG} values are calculated for a certain number of combination of test intervals.					
β factors	 β=β_D=0,05 The above values for of to IEC 6150 The above valued redundancy The β factors can be above to IEC 6150 	 β=β_D=0,05 The above value is the value for 1oo2 architecture. The values for other architectures shall be calculated according to IEC 61508 Part 6, Table D.5. 					
MRT	1 h The MRT considit takes in considered						
PTC	The procedure to Manual.	for the Proof Tes	t is described in	the Safety			
Architectural constraints	o up to S	n be used in: nel configuration SIL 2 without exte SIL 3 considering nnel configuration	ernal diagnostic external diagno				

TÜV INTERCERT S.r.l. – Group of TÜV Saarland

Via Cecati 1/1 I-42123 Reggio Emilia e-mail: info@tuvintercert.it

Report no.: RC-0818-SIL-TIC-PC-0010024-18-02

Rev.: Job no.: TIC-PC-0010024-18-0077-18 Order no: Emerson order dated 2018-06-13



Expected lifetime	10 years
Behaviour of the safety function under fault conditions	The product does not include internal diagnostics.
Safety related SW	No SW is used to implement the safety function.
Systematic Capability	3
Behaviour under environmental conditions Limitations for use	The behaviour in environmental conditions is assessed evaluating the relevant environmental tests. Make reference to the Safety Manual.

Remarks

- The random failure rates in the above table are valid for all the possible configurations of the product.
- According to the definition of IEC 61508 (in particular definitions 3.6.8 and 3.6.13 of IEC 61508 Part 4), no Safe Failures are possible in a single acting actuator: each failure mode of the actuator itself shall be classified as "Dangerous" or "No Effect" (failures which can generate the spurious operation of the safety function are only external to the actuator itself, or are related to components that "play no part in implementing the safety function"); hence, λ_S=0 for each type of single acting actuator.
- Failures of components of the cylinder which can generate spurious trips shall be correctly classified as "No Part" and not "Safe", being related to components that "play no part in implementing the safety function" (see definition 3.6.16 of IEC 61508 Part 4).

 Anyway the spurious trip rate is estimated.
- The λ_S values are not divided in λ_{SD} and λ_{SU} , as this subdivision has no relevance for any of the SIL parameters.
- For further details, make reference to the Safety Manual.

Reference documents SIL Assessment Report TÜV INTERCERT document no. RC-0818-SIL-TIC-PC-0010024-18-01 Safety Manual Emerson document no. DOC.SILM.EF.EN

3 STATUS OF THE DOCUMENT

History: R 00: Initial release Date: 2018-08-07

Release Released to client

status:

Author(s): Carlo Tarantola

TÜV INTERCERT S.r.l. – Group of TÜV Saarland Report no.: RC-0818-SIL-TIC-PC-0010024-18-02

Via Cecati 1/1 Rev.:

I-42123 Reggio Emilia Job no.: TIC-PC-0010024-18-0077-18 e-mail: info@tuvintercert.it Order no: Emerson order dated 2018-06-13

Page 5 of 7



ANNEX A - EXAMPLES OF PFDAVG CALCULATIONS

Type: F - No PST - Safety function: 1

Proof test interval (months)						
6 12 24 36 48						
5,64E-05 1,12E-04 2,24E-04 3,36E-04 4,47E-04						

Type: F - With PST - Safety function: 1

		Proof test interval (months)						
		6	6 12 24 36 48					
	1	1,41E-05	1,91E-05	2,92E-05	3,92E-05	4,93E-05		
val s)	2	2,26E-05	2,76E-05	3,76E-05	4,77E-05	5,77E-05		
interva onths)	3	3,10E-05	3,61E-05	4,61E-05	5,62E-05	6,62E-05		
	6		6,15E-05	7,15E-05	8,16E-05	9,16E-05		
m)	9				1,07E-04			
-	12			1,22E-04	1,32E-04	1,42E-04		

NOTES:

- The above values of PFD_{AVG} are calculated for MRT=24 h and proof test coverage=100%. For other values of MRT, TI, TI_{PS} and/or non-perfect proof test, the PFD_{AVG} values must be re-calculated.
- The PFD_{AVG} values including partial stroke test are calculated considering the use of a commercial automatic partial stroking test system: for further details, see the Safety Manual.

The values in the above tables are compatible with SIL 3.

Rev.: 00 Job no.: TIC-PC-0010024-18-0077-18 Order no: Emerson order dated 2018-06-13

RC-0818-SIL-TIC-PC-0010024-18-02

Report no.:

Page 6 of 7



ANNEX B - ABBREVIATIONS AND DEFINITIONS

Term	Meaning
β, β _D	Beta common cause factor
λвв	"Black Box" Failure rate – Literature data
λ_{D}	Failure rate of dangerous failures
λ_{DD}	Failure rate of detected dangerous failures
λ_{DU}	Failure rate of undetected dangerous failures
λ _{NE}	Failure rate of no effect failures
λ_{S}	Failure rate of safe failures
λss	"Steady State" Failure rate – Final Value
DC	Diagnostic coverage
FMEDA	Failure modes, effects and diagnostic analysis
HFT	Hardware fault tolerance
High demand mode	Mode, where the frequency of demands for operation made on a safety- related system is greater than one per year
Low demand mode	Mode, where the frequency of demands for operation made on a safety- related system is no greater than one per year
MRT	Mean repair time
PFD	Probability of failure on demand
PFD _{AVG}	Average probability of failure on demand
PFH	Probability of failure per hour
PST	Partial stroke test
PTC	Proof test coverage
SFF	Safe failure fraction
SIF	Safety instrumented function
SIL	Safety integrity level
SIS	Safety instrumented system
SLC	Safety lifecycle
SRS	Safety requirements specification
TI	Test interval for proof test (full stroke)
TI _D (TI _{PS})	Test interval for diagnostic test (partial stroke)
Туре А	"Non-complex" element (using only discrete components to implement the safety function)
Туре В	"Complex" element (using also micro controllers or programmable logic to implement the safety function)

For definitions, standard IEC 61508 (in particular Part 4) applies.

TÜV INTERCERT S.r.l. – Group of TÜV Saarland

Via Cecati 1/1

I-42123 Reggio Emilia e-mail: info@tuvintercert.it Report no.: RC-0818-SIL-TIC-PC-0010024-18-02

Rev.: 00

Job no.: TIC-PC-0010024-18-0077-18
Order no: Emerson order dated 2018-06-13

子

5



Certificate no.

18-SIL-0010024-03-TIC

WE HEREBY CERTIFY THAT

Product description

EL-O-MATIC™ PNEUMATIC RACK AND PINION SPRING

RETURN ACTUATORS

Models

SERIES F (from size 0950 up to and including size 4000)

EMERSON AUTOMATION SOLUTIONS

Valve Automation, Inc.

Manufacturer

19200 NW Freeway

Houston, TX 77065

USA

IS IN COMPLIANCE WITH THE REQUIREMENTS OF THE STANDARDS

IEC 61508 Parts 1-7:2010

AS RESULT OF THE ASSESSMENT ACCORDING TO THE PROVISION

SET OUT IN THE ABOVE-MENTIONED STANDARDS

Summary Report no. RC-0120-SIL-TIC-PC-0010024-18-02

Expiry date

29.01.2023

Note

This certificate is issued upon the request of the manufacturer as voluntary certification; it does not include the production surveillance.

This certificate does not allow the manufacturer to use the safety mark of TÜV INTERCERT.

Reggio Emilia, 30.01.2020



Dipl. Ing. Feridoon Sergizzarea TÜV INTERCERT Certification Body

인증서



CERTIFICATE

ANNEX to Certificate no. 18-SIL-0010024-03-TIC

Туре	A
HFT	0
Safety functions	 Delivery of a full stroke (90° ± tolerance) driven by the spring, with power fluid exhausted from the cylinder through the control system
Mode of operation	Low Demand Mode

Random failure rates						
Configuration	Safety function	λ _{DU} [1/h]	λ _{DD} [1/h]	λ _S [1/h]		
F - No PST	1	2,61E-08	0,00E+00	0,00E+00		
F - With PST	1	2,34E-09	2,37E-08	0,00E+00		

Systematic capability	3 (Route 1 _S applied)			
	Route 1 _H :	Applied	Route 2 _H :	Applied
Architectural constraints	single chai up to SI up to SI	The product can be used in: • single channel configuration: • up to SIL 2 without external diagnostic tests • up to SIL 3 considering external diagnostic tests • double channel configuration: up to SIL 3		

Remarks:

 For further details, including environmental conditions, limitations of use, lifetime, failure rates traceability, mean repair times, common cause factors and systematic capability constraints, make reference to Safety Manual DOC.SILM.EF.EN.

END OF CERTIFICATE

Reggio Emilia, 30.01.2020

Dipl. Ing. Feridoon Sergizzarea

TÜV INTERCERT Certification Body

Page 2 of 2



TÜV INTERCERT S.r.l. - Group of TÜV Saarland

Report no.: RC-0120-SIL-TIC-PC-0010024-18-02

SIL SUMMARY REPORT

IEC 61508-1/7:2010

EL-O-Matic™ pneumatic rack and pinion spring return actuators

Series F (from size 0950 up to and including size 4000)

> **Emerson Automation Solutions** Valve Automation, Inc. 19200 NW Freeway Houston, TX 77065 USA

Date: 2020-01-27 Place: Reggio Emilia

> Author Carlo Tarantola

This document is only valid in its entirety, without any change.

TÜV INTERCERT S.r.l. - Group of TÜV Saarland RC-0120-SIL-TIC-PC-0010024-18-02 Report no.:

Via Cecati 1/1

Rev.: TIC-PC-0010024-18-0080-18 I-42123 Reggio Emilia Job no.: Emerson order dated 2018-07-17 e-mail: info@tuvintercert.it Order no:

Page 1 of 7



1 INTRODUCTION

This report summarises the results of the assessment according to standards:

IEC 61508-1/7:2010

for the following products:

EL-O-Matic[™] pneumatic rack and pinion spring return actuators series F (from size 0950 up to and including size 4000)

NOTES:

- This report is related to the assessment of EL-O-Matic[™] pneumatic rack and pinion spring return actuators series F from size 0950 up to and including size 4000.
- The results of this report can be used for the assessment of a complete Safety Instrumented System.

2 ASSESSMENT AND RESULTS

Product identification					
Device	EL-O-Matic	r™ pneumatic rack and pinion spring return			
Series	F				
Models / configurations	F - No PST F - With PST				
Safety function(s)					
1.	with power control syst NOTE: con the safety f can be con-	a full stroke (90° ± tolerance) driven by the spring, fluid exhausted from the cylinder through the tem. sidering the functioning of the actuator to perform unction(s), the safety functions "close" and "open" sidered equivalent. The safety function is in both en by the spring.			
Mode of operation of the safety function(s)	Low demand mode				
Reference standards					
General functional safety standard	IEC 61508-	-1/7:2010			
Product specific functional safety standard	None				
Assessment phases					
Management of functional safety / functional safety planning	Assessed	A functional safety audit of the management systems and of the functional safety planning is conducted to document and highlight that the development of the product under consideration is compliant with IEC 61508.			

TÜV INTERCERT S.r.I. – Group of TÜV Saarland Report no.: RC-0120-SIL-TIC-PC-0010024-18-02

Via Cecati 1/1 Rev.: 0

I-42123 Reggio Emilia

e-mail: info@tuvintercert.it

Job no.: TIC-PC-0010024-18-0080-18

Emerson order dated 2018-07-17



	T	I	
Safety requirements specification	Assessed	The Safety requirements specification is assessed with respect to its consistency and completeness in a comparison with the applicable requirements of IEC 61508.	
Design	Assessed	 The assessment of the design included the following aspects: Quantifiable aspects: random failure rates, DC, SFF, PFD_{AVG}, β factors, MRT, PTC, architectural constraints Non-quantifiable aspects: behaviour of the safety function under fault conditions, safety-related software (not applicable to the product under consideration), systematic failures, behaviour under environmental conditions See below for the results. 	
Verification and Validation	Assessed	The verification and validation activities performed by the manufacturer include review, analysis and tests.	
Information for use	Assessed	 The assessment covers: the installation, operation and maintenance instructions (IOM Manual) the particular instructions required by Annex D of IEC 61508 Part 2 (Safety Manual) 	
Modification	Assessed Procedures for modification activity are described in specific documents, referenced in the safety planning.		
Results			
Selected assessment routes	 For System Furthermon 7.4.10.7 of fulfilled, as the propand is continuous the propand	duct has a restricted and specified functionality designed to perform specified safety functions duct has an adequate documentary evidence ng extensive operating experience and results of ity analysis and testing), sufficient to claim the defailure rates nufacturer has an effective system for reporting	
Element type (A or B)	Type A		
HFT	The produc	ct has a single channel configuration, HFT=0.	

Via Cecati 1/1
I-42123 Reggio Emilia
e-mail: info@tuvintercert.it

Rev.: 00
Job no.: TIC-PC-0010024-18-0080-18
Order no: Emerson order dated 2018-07-17



Random failure rates	The determination of random failure rates is performed with a FMEDA, integrated with field feedback, according to IEC 61508 Part 2 Par. 7.4.4.3.3, using the Bayesian approach.				
Configuration	Safety function	λ _{DU} [1/h]	λ _{DD} [1/h]	λ _s [1/h]	
F - No PST	1	2,61E-08	0,00E+00	0,00E+00	
F - With PST	1	2,34E-09	2,37E-08	0,00E+00	
Spurious trip rate	generate spurio Part" and not "S no part in imple 3.6.16 of IEC 6 ² estimated.	NOTE: failures of components of the cylinder which can generate spurious trips shall be correctly classified as "No Part" and not "Safe", being related to components that "play no part in implementing the safety function" (see definition 3.6.16 of IEC 61508 Part 4). Anyway the spurious trip rate is			
DC	Diagnostic is on PST.	The product does not include internal diagnostics. Diagnostic is only be possible via external means, e.g. with a PST. The procedure for the PST is described in the Safety Manual.			
SFF	Considering tha 61508 Part 4: SFF=0 without SFF>0 with to definition	Considering that λ_S =0, according to definitions 3.6.15 of IEC			
PFD _{AVG}	As the PFD _{AVG} value depends also on the test intervals and on the PTC and the coverage of external tests, which are not product-dependant quantities, the PFD _{AVG} values are not product relevant quantities, while λ values are. Anyway, PFD _{AVG} values are calculated for a certain number of combination of test intervals. See Annex A.				
β factors	 β=β_D=0,05 The above value is the value for 1oo2 architecture. The values for other architectures shall be calculated according to IEC 61508 Part 6, Table D.5. The above value is calculated in the hypothesis of redundancy without diversity The β factors can be used when performing PFD_{AVG} calculations for redundant architectures. 				
MRT	1 h The MRT considered is the Technical Mean Repair Time, i.e., it takes in consideration availability of skilled personnel, adequate tools and spare parts.				
PTC	The procedure for the Proof Test is described in the Safety Manual.				
Architectural constraints	The product can be used in: single channel configuration: up to SIL 2 without external diagnostic tests up to SIL 3 considering external diagnostic tests double channel configuration: up to SIL 3				

TÜV INTERCERT S.r.l. – Group of TÜV Saarland Via Cecati 1/1 I-42123 Reggio Emilia e-mail: <u>info@tuvintercert.it</u>

RC-0120-SIL-TIC-PC-0010024-18-02 Report no.:

Rev.: Job no.: TIC-PC-0010024-18-0080-18 Emerson order dated 2018-07-17 Order no:



Expected lifetime	10 years
Behaviour of the safety function under fault conditions	The product does not include internal diagnostics.
Safety related SW	No SW is used to implement the safety function.
Systematic Capability	3
Behaviour under environmental conditions Limitations for use	The behaviour in environmental conditions is assessed evaluating the relevant environmental tests. Make reference to the Safety Manual.

Remarks

- The random failure rates in the above table are valid for all the possible configurations of the product.
- According to the definition of IEC 61508 (in particular definitions 3.6.8 and 3.6.13 of IEC 61508 Part 4), no Safe Failures are possible in a single acting actuator: each failure mode of the actuator itself shall be classified as "Dangerous" or "No Effect" (failures which can generate the spurious operation of the safety function are only external to the actuator itself, or are related to components that "play no part in implementing the safety function"); hence, λ_S=0 for each type of single acting actuator.
- Failures of components of the cylinder which can generate spurious trips shall be correctly classified as "No Part" and not "Safe", being related to components that "play no part in implementing the safety function" (see definition 3.6.16 of IEC 61508 Part 4). Anyway the spurious trip rate is estimated.
- The λ_S values are not divided in λ_{SD} and λ_{SU} , as this subdivision has no relevance for any of the SIL parameters.
- For further details, make reference to the Safety Manual.

Reference documents SIL Assessment Report TÜV INTERCERT document no. RC-0120-SIL-TIC-PC-0010024-18-01 Safety Manual Emerson document no. DOC.SILM.EF.EN

3 STATUS OF THE DOCUMENT

History: R 00: Initial release Date: 2020-01-27

Release status: Released to client Author(s): Carlo Tarantola

TÜV INTERCERT S.r.I. – Group of TÜV Saarland Report no.: RC-0120-SIL-TIC-PC-0010024-18-02

Via Cecati 1/1 Rev.:

I-42123 Reggio Emilia

e-mail: info@tuvintercert.it

Job no.: TIC-PC-0010024-18-0080-18

Emerson order dated 2018-07-17

Page 5 of 7



ANNEX A - EXAMPLES OF PFDAVG CALCULATIONS

Type: F - No PST - Safety function: 1

Proof test interval (months)						
6	12 24 36 48					
5,77E-05	5,77E-05 1,15E-04 2,29E-04 3,43E-04 4,57E-04					

Type: F - With PST - Safety function: 1

		Proof test interval (months)				
		6	12	24	36	48
	1	1,44E-05	1,95E-05	2,98E-05	4,01E-05	5,04E-05
val s)	2	2,31E-05	2,82E-05	3,85E-05	4,87E-05	5,90E-05
interva onths)	3	3,17E-05	3,69E-05	4,71E-05	5,74E-05	6,77E-05
	6		6,28E-05	7,31E-05	8,34E-05	9,36E-05
m)	9				1,09E-04	
_	12			1,25E-04	1,35E-04	1,46E-04

NOTES:

- The above values of PFD_{AVG} are calculated for MRT=24 h and proof test coverage=100%. For other values of MRT, TI, TI_{PS} and/or non-perfect proof test, the PFD_{AVG} values must be re-calculated.
- The PFD_{AVG} values including partial stroke test are calculated considering the use of a commercial automatic partial stroking test system: for further details, see the Safety Manual.

The values in the above tables are compatible with SIL 3.

I-42123 Reggio Emilia e-mail: info@tuvintercert.it

Report no.: RC-0120-SIL-TIC-PC-0010024-18-02

Rev.: 00

Job no.: TIC-PC-0010024-18-0080-18
Order no: Emerson order dated 2018-07-17

Page 6 of 7



ANNEX B - ABBREVIATIONS AND DEFINITIONS

Term	Meaning		
β, β _D	Beta common cause factor		
λвв	"Black Box" Failure rate – Literature data		
λ_{D}	Failure rate of dangerous failures		
λ_{DD}	Failure rate of detected dangerous failures		
λ_{DU}	Failure rate of undetected dangerous failures		
λ _{NE}	Failure rate of no effect failures		
λ_{S}	Failure rate of safe failures		
λss	"Steady State" Failure rate – Final Value		
DC	Diagnostic coverage		
FMEDA	Failure modes, effects and diagnostic analysis		
HFT	Hardware fault tolerance		
High demand mode	Mode, where the frequency of demands for operation made on a safety- related system is greater than one per year		
Low demand mode	Mode, where the frequency of demands for operation made on a safety- related system is no greater than one per year		
MRT	Mean repair time		
PFD	Probability of failure on demand		
PFD _{AVG}	Average probability of failure on demand		
PFH	Probability of failure per hour		
PST	Partial stroke test		
PTC	Proof test coverage		
SFF	Safe failure fraction		
SIF	Safety instrumented function		
SIL	Safety integrity level		
SIS	Safety instrumented system		
SLC	Safety lifecycle		
SRS	Safety requirements specification		
TI	Test interval for proof test (full stroke)		
TI _D (TI _{PS})	Test interval for diagnostic test (partial stroke)		
Туре А	"Non-complex" element (using only discrete components to implement the safety function)		
Туре В	"Complex" element (using also micro controllers or programmable logic to implement the safety function)		

For definitions, standard IEC 61508 (in particular Part 4) applies.

TÜV INTERCERT S.r.l. - Group of TÜV Saarland

Via Cecati 1/1

I-42123 Reggio Emilia e-mail: info@tuvintercert.it

RC-0120-SIL-TIC-PC-0010024-18-02 Report no.:

Rev.:

TIC-PC-0010024-18-0080-18 Job no.: Emerson order dated 2018-07-17 Order no: